

Document Number : IB-24-18

Released Date : 2024.07.15

Recipient : Domestic sales, Overseas sales

Reference : Quality Part, Production Part

Title : Change in the Display Front and the LCD Bracket of InBody270

1. We are much appreciated for the hard work from branches and subsidiaries.

2. Change Classification (Reason)

The screw position has been changed to address the issue where the interference of the LCD Bracket and the Display Front damages the LCD FFC Cable during the manufacturing process.

3. Changed Details

Before	After
	
	

Headquarter : InBody Bldg., 625, Eonju-ro, Gangnam-gu, Seoul 06106 Korea

Manufacturer : 15, Heugam-gil, Ipjang-myeon Seobuk-gu, Cheonan-si Chungcheongnam-do 31025 KOREA

Tel : 010-9909-2372

Fax : (041)581-3103

Department in charge : Quality Management Team of Quality Part

Person in charge : TaeGu Kang E-mail : kp016250@inbody.com

IB-105-035

InBody Co., Ltd

Rev.0

[Details]

Division	Before	After
Picture		
Name (Item Code)	M_LCD Bracket New 270 EMI (I10101324)	M_LCD Bracket New InBody270 Rev.1 (I10101455)
Picture		
Name (Item Code)	P_Display Front New EMI 270 (I10301653)	P_Display Front New 470/270 Rev.1 (I10301891)

4. CS Plan

Since the changed parts are not compatible with the old spare parts, both the LCD Bracket and the Display Front must be replaced as a pair.

5. Date of Implementation

Model	S/N	Manufacture Date
InBody270	F924003191	2024-05-28

Headquarter : InBody Bldg., 625, Eonju-ro, Gangnam-gu, Seoul 06106 Korea

Manufacturer : 15, Heugam-gil, Ipjang-myeon Seobuk-gu, Cheonan-si Chungcheongnam-do 31025 KOREA

Tel : 010-9909-2372

Fax : (041)581-3103

Department in charge : Quality Management Team of Quality Part

Person in charge : TaeGu Kang E-mail : kp016250@inbody.com

IB-105-035

InBody Co., Ltd

Rev.0