

Document number: BP-24-08

Released Date: 2024.05.23

Recipient: Sales team, Overseas branches and subsidiaries / Blood Pressure Monitor Department

Reference: Quality Management Team, Manufacturing Technology Team, CS team

Title: Share Change History - InBody BPBIO320/750 Cal Rubber Cap

결	작 성	검 토	승 인
재			



1. We much appreciate the hard work from branches and subsidiaries.

2. Notification Purpose

Due to the issue of the Cal Rubber Cap detaching from the BPBIO320/750 products, we are sharing the history of changes as follows.

3. Application equipment

InBody BPBIO320 / InBody BPBIO750

4. Change History:

1) InBody BPBIO320/750 Cal Rubber Cap shape modification



<Before>



<After>



<Applied Pictures>

(Left: BPBIO320, Right: BPBIO750)

Headquarter: InBody Bldg., 54 Nonhyeon-ro 2-gil, Gangnam-gu, Seoul, 06313 Korea

Manufacturer: 330 Yeongok-gil, Ipjang-myeon Seobuk-gu, Cheonan-si Chungcheongnam-do 31026 Korea

Tel: 010-4929-6872

Fax: (041)581-3103

Department in charge: Quality Management Team / Blood Pressure Monitor Department

Person in charge: San Kang

E-mail: san.kang@inbody.com

5. Production Application time

Product Name	Production date	S/N
BPBIO 320	2024/05/20	8224000295

- The changes will be applied from the product manufactured on May 20, 2024, with S/N 8224000295.

Product Name	Production date	S/N
BPBIO 750	2024/05/23	H224000567

- The changes will be applied from the product manufactured on May 23, 2024, with S/N H224000567.

- End of Document -